

Rennacs® CodeReader™ Diagnostic Test Results

Operator: Rennacs
Date: 08/16/10
Time: 15:18:59
Invoice Number: 3241

Customer: Joe Bloggs
Vehicle: Toyota Camry
Registration: AAA123

- 12 Engine speed signal (NE or G), no signal to Electronic Control Unit / CKP/CMP sensor
- 23 Intake Air Temperature sensor or circuit.

Charge: \$50.00

Total: \$50.00

CodeReader Information is Copyright © Rennacs Ltd
Rennacs accept no liability for any mistake in, or misuse of this information.